Inspection Report

Name of Work	**Maintenance of Water Supply Existing Pump and Motor repair of Pipe Lines providing additional new pumps motors gatewall, and other Accoriseries in Thanisandra Surrounding Area in Ward No. 06 Byatarayanapura Sub Division**
Work order	**EE/BTP/BBMP/E-PMT/369/14-15, Dt.24.03.2015**
Agency	**Sri. H.V Nagaraj**
B.R, No and Date	**302, Dt.31.03.2016**
Bill Amount	**31,33,94.50**
Job Code	**006-15-000020**
P. Code	**P1802**
Date of Inspection	

The above said work "Maintenance of water supply existing pump and motor repair of pipe lines providing additional new pumps motors, gate wall, and other Accessories in Thanisandra surrounding area in ward no 06 Byatarayanapura Sub div" was shown to me by the Concerned ward Engineer.

The work is inspected by me along with the Concerned ward Engineer.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಕೆ.ಬಿ.ಎಚ್.ಪಿ. ಚ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ



MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಅಭಿಯಂತರರು

ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ